



Picture 1 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Manure pit.



Picture 2 – Allandra Farm, 1535 Monkton Rd, Ferrisburgh, VT – 09/19/13  
Agitation equipment in concrete manure collection pit below the main barn.





Picture 3 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Used bedded pack pile located outside the main barn.



Picture 4 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Outside 1,000 gallon tank associated with the older milking parlor.





Picture 5 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Silage bunkers located next to the main barn and manure pit.



Picture 6 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Corn silage bunker.





Picture 7 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Leachate pooling over a drain at the back of the silage bunkers.



Picture 8 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Drainage ditch that receives some runoff from the back side of silage bunkers.





Picture 9 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Vegetated area off Middlebrook Rd. which receives runoff from the farm ditch (in picture #8).



Picture 10 – Allandra Farm, 1535 Monkton Rd., Ferrisburgh, VT – 09/19/13  
Compost pile located north of the heifer barn.